017-170 - McDowell Dam Bank Stabilization - 2020

Status Report Details

Funding Opportunity: 3515-Outdoor Heritage Fund September 2020 - Round 17 **Program Area:** Outdoor Heritage Fund Status: Submitted **Status Report Number:** 006 **Status Report Type:** Interim **Reporting Period:** 07/23/2021 - 10/20/2021 **Initial Submit Date:** Dec 20, 2021 1:59 PM **Initially Submitted By:** Travis Johnson **Last Submit Date:** Last Submitted By: **Approved Date:** Approved By: **Contact Information Primary Contact Information** Active User*: Yes **External User** Type: Name: Mr. **Travis** Middle Name Johnson Salutation First Name Last Name Title: Civil Engineer Email*: tjohnson@houstoneng.com Address*: 3712 Lockport Street Bismarck North Dakota 58503 City State/Province Postal Code/Zip Phone*: (701) 226-0227 Ext.

Phone

###-###-#### (701) 323-0300

###-###-####

Comments:

Fax:

Organization Information Status*: Approved Name*: **Burleigh County Water Resource District** Organization Type*: **County Government** Tax Id: **Organization Website:** Address*: 1926 Frontier Drive, Suite B Bismarck North Dakota 58504-0000 State/Province Postal Code/Zip Phone*: (701) 222-3499 Ext. ###-###-#### Fax: ###-###-#### Benefactor: **Vendor ID: PeopleSoft Supplier ID: Comments: Location Code: SAM.gov Entity ID:** SAM.gov Name: **SAM.gov Entity ID Expiration** Date: State Issued ID: Category #: Year Begin: Year Closed: NCES#: **Restricted Indirect Cost Rate:** 0.0% **Unrestricted Indirect Cost Rate:** 0.0%

Document Approval

Level Approved By Approved Date Approval Comments

Interim Report

Interim Report

Work Accomplished*:

The Contractor work for this project was completed during the time period from September 20th to September 22nd. The trees were also delivered to the Park District shop and work began on installing the trees utilizing Park District staff and equipment. The Park District also accomplished the trail relocation portion of the project, again utilizing their own staff and equipment. As of this writing, the disturbed area has been reclaimed and seeded, and the trees have been planted.

Certification

This report was prepared pursuant to an agreement with the Industrial Commission of North Dakota, which partially funded the project through the Outdoor Heritage Fund. Project participants, its subcontractors, and the Industrial Commission of North Dakota, or any person acting on its behalf, do not:

- **(A)** Make any warranty or representation, express or implied, with respect to the accuracy, completeness, or usefulness of the information contained in this report, or that the use of any information, apparatus, method, or process disclosed in this report may not infringe privately-owned rights; or
- **(B)** Assume any liabilities with respect to the use of, or for damages resulting from the use of, any information, apparatus, method or process disclosed in this report.

Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the Industrial Commission of North Dakota. The views and opinions of authors expressed herein do not necessarily state or reflect those of the Industrial Commission of North Dakota.

Do you agree?*:

Photos

Description	File Name	Type	Size	Upload Date
Completed Riprap placement	KIMG2186.JPG	JPG	995 KB	12/20/2021 01:56 PM
Completed Riprap Placement2	KIMG2182.JPG	JPG	744 KB	12/20/2021 01:57 PM

Tasks Report

Tasks

		Completion	Percent	
Task	Start Date	Date	Complete	Comments
Project Design	01/01/2021	01/31/2021	100.0%	Design has been completed.
Solicitation of	02/01/2021	02/28/2021	100.0%	Solicitation of quotes and Contractor
Quotes/Contractor Selection				selection has been completed.
Project Construction	04/01/2021	06/30/2021	100.0%	Project construction has been completed.

Description of Tasks

Please Describe Tasks:

Deliverables Report

Deliverables

Deliverable	Unit of Measurement, if Quantity applicable	Status
Expenditure Report	1.000	Expenditure report has been submitted.
Final Project Acceptance	1.000	Project has been accepted by Owner.
Monthly Construction Progress Report	3.000 Each	Status reports have been submitted.



